

# ANNUAL SURVEYS.

4111

Recd 24.9.75.

No. in Register 725 on the Brig. Eother Survey held at Glasgow Date 22<sup>nd</sup> Sept. 1875  
 Tonnage 215.55 Built at Cardiff Master W. McKenzie  
 When built 1849 Owners D. McKenzie of Stornoway  
 Port belonging to Stornoway Destined Voyage Clyde to Spain  
 Surveved Afloat or in Dry Dock Afloat  
 Registered Dimensions 94.4 x 24.4 x 15.1

Under Deck 216.95  
 Break 8.72  
 Gross 225.67  
 Crew Space 10.12  
 Register 215.55

Last Survey, No. <u>91</u>		Port of <u>Orkneys</u>		Classed <u>12</u>	
The present Condition of the					
Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>Good &amp; efficient</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Sails	<u>Well Found</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Anchors, No. of	<u>3 B. 15. 2 K</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Cables	<u>Complete</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Hawsers and Warps	<u>Well Found.</u>
Wales	<u>do</u>	Rudder	<u>As seen afloat</u>	Standing and Running Rigging	<u>In good order</u>
Plank (Bottom) and Counter	<u>do as far as seen afloat</u>	Copper	<u>Single</u>	When put on	<u>not sheathed</u>
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways <u>As far as seen good</u>			

Is in good and efficient condition eligible to be re-entered in the Register as classed in Register for 1874-75  
A 1 S.S. Ork. 72-8 yrs

Committee's Minute 28<sup>th</sup> September 1875  
 Character assigned A 1 in reg  
 Certificate (if required). 5/2

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveved Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. _____		Port of _____		Classed _____	
The present Condition of the					
Decks	_____	Treenails	_____	Windlass and Capstan	_____
Waterways	_____	Breasthooks and Stemson	_____	Pumps	_____
Comings	_____	Transoms, Pointers, and Crutches	_____	Boats	_____
Upper Deck Beams & Fastenings	_____	Timbers of the Frame at the Openings	_____	Masts, Yards, &c.	_____
Lower Deck Beams & Fastenings	_____	Ditto ditto at other places	_____	Sails	_____
Planksheers	_____	Keelsons	_____	Anchors, No. of	_____
Sheerstrakes	_____	Clamps and Shelves	_____	Cables	_____
Topsides	_____	Ceiling	_____	Hawsers and Warps	_____
Wales	_____	Rudder	_____	Standing and Running Rigging	_____
Plank (Bottom) and Counter	_____	Copper	_____	When put on	_____
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways _____			

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_