

REPORT of SURVEY for REPAIRS, &c.

No. 5824

No. in Survey held at Glasgow

Reg. Book.

941 on the S. S. "Granmore"

Date, first Survey 29th Aug

Last Survey 7th Sept 1882

(No. of Visits)

Master J. Hetherington

YEAR.

MONTH.

1881

4

When built

Built at

Perth

Owners

Glyde Shipping Co

Port belonging to

Glasgow

Residence

By whom built W. Simons & Co

Destined Voyage

Coaster

If Surveyed Afloat & in Dry Dock

(State Name of Dock)

Hendersons Dock

Official Number 84316

TONNAGE under Tonnage Deck

736

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Or. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

833

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St mer, cut on Bm.

419

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Classed

100 A1

2.82

Last Survey, No.

5623

Port

Gls

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Damage from striking a Quay Wall.

Now Done. The vessel having been placed in Graving Dock it was found that the Stern Post was slightly cracked about 18 inches above the Keel & 1 Rudder Pin broken, in consequence the Stern frame has been taken out welded & replaced & the Rudder Pin renewed. The Bottom cleaned & coated.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Gord

Timber

Gord

Windlass and Capstan

Gord

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder Repaired

Copper (or Zinc) Paint When put on Now

Caulking of

Bottom, Deck, & Waterways

Pumps

Boats 4

Masts, Yards, &c.

Condition, how ascertained On Deck

Sails Well found

Anchors No. of 3B. 15. 2 R

Cables Said to be complete

Hawsers and Warps Well found

Standing & Running Rigging Efficient

Cargo and Main Hatchways Gord Hatches Gord

The above named repairs having been efficiently executed & the vessel otherwise appearing in good condition, I am of opinion she is eligible to remain as classed.

The Amount of Entry Fee ... £ : :

Special ... £ 2 : 2 :

received by me,

14/9/1882

Certificate (if required)

to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Tuesday, 12th September 1882

100 ... TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019 Lloyd's Register Foundation

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.

(If a Steam Ship, state if a Report is also sent on the Machinery.)

[Form No. 2 for Repairs.—4,000—20/5/82.]

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)