

6760 Gls
Planned

Geo

Geo

yes

03e

a few in butts only

P. Pine in good

Reference should be made to any correspondence connected with the case.

The Windlass is *T. Rind & Sons* Capstan *✓* and Rudder *Good* Pumps *Good*

What arrangements for deadlights in bad weather? *Strong Canvas covers*

Scunnors &c — What arrangements for clearing upper deck of water, in case of shipping a sea? *One morning life line scuppers and*

Cargo Hatchways.—How formed? *Plates and Arcs*

If of extraordinary size state how framed and secured? *Not of extraordinary size*

Hatches: If strong and efficient? *See mid .3" thick*

Order for Special Survey No. 1952 yrs pgs 8. 1st. On the several parts of the frame, when in 1884: 20-25 June 14-97. 4-10-100

3rd. When the beams were in and fastened,) 2, 9, 11, 17, 21 Oct. 7. 4, 13, 18, 20, 24

Date 3-3

DATE 3-3 would have been per...
plating was finally coated or cemented.. }

State dates of letters respecting this case 29: May & 3: Sep: 1884.

General Remarks (State quality of material, etc.)

Sketches herewith returned and Secretary's letters of above dates

The has a gonorrhea 20.0, May 1.0

It is also tested by water measure as required.

the Rules and proved satisfactory. The after compar

.....

.....

.....

1890

How are the surfaces preserved from oxidation? Inside Cement and Tank Outside Tank

The amount of the Entry Fee£ 2 : - : - is received by me,) *[Signature]*

(to be sent as per margin) Certificate ... : : : :
Surveyor to Lloyd's Register of British and Foreign Shipping

Committee's Minute

Character assigned: 111