

8344
Report of Survey for Repairs, &c., of Engines & Boilers.

No. 8344 Port of Glasgow (Received at London Office, FRIDAY 2 MARCH 1888)
No. in Survey held at Glasgow Date, first Survey Feb 25th Last Survey Feb 27th 1888
Reg. Book. 611 on the Machinery of the S.S. Borghese (Number of Visits Two)

Tonnage, Gross 1331 Built at Sunderland When built 1870 11
Ditto, Net 2044 Owners Racburn & Virel Port belonging to Glasgow
Diameter of Cylinder 36 7/8 + 64 Engines made by J. Howden & Co When made 1882
Length of Stroke 42 Boilers made by ✓ When made 1882
Pressure of Steam 80 lbs If Surveyed Afloat or in Dry Dock ✓ Character in Register Book.
Registered Horse Power 200 (State Name of Dock.) Classed 100A.1.8-87.
Last Survey No. 8719 Port Npt L.M.C. 8-87.

Particulars of Repairs and Examination
(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Examined while rough turning & finishing a new propeller shaft for this vessel at the works of Messrs D & W Henderson.

General Observations, Opinion, and Recommendation :—
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

This new shaft appeared to be of good material & workmanship - it has been finished complete and shipped to Buenos Ayres to be fitted on board the vessel.

Office or Registration Fee (per Sec. 27) £ : :
Survey Fee (per Section 28) £ 1 : 1
Special on Damage, Fee (per Section 28) £ : :
*Certificate (if required) to be sent as per margin. £ : :
Travelling Expenses (if chargeable) £ : :
received by me, 173/ 1888 Walter E. Robson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute TUES 6 MARCH 1888
Assigned No new record on this report
Lloyd's Register Foundation GLS 55-0081

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

8377 GL

It is submitted that
this should be considered
satisfactory.

AF

5.3.88

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation