

15831

21/7/91

Repairs on account of Damage should be separated from

Repairs on account of Damage should be separated from

No

Do

Not required

✓

✓

14

✓

✓

✓

When this vessel was in dry dock, the

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon the survey thus, for example, B.S. 1.89, B.&M.S. 1.89, or ☒ L.M.C. 1.89, as the case may be.)

Fees applied for

Received by me,

R. J. Pennington
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping

FRI 24 JUL 1891

As now

Glasgow

Lloyd's Register
Foundation

GLS162-0308

10831 90

It is submitted that this vessel
is eligible for remain as classed.

C.P.

21.7.91

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.



© 2019

Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO

CROSS THIS MARGIN.