

GLS 169-0102



12691 Gls

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for

THE RECORD B.S. 1-94

On acct of a propeller blade being

broken—

a new propeller was

fitted

W.A.

25-1-94



© 2019

Lloyd's Register  
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.