

# Report of Survey for Repairs, &c., of Engines and Boilers.

No. 13945

THUR 19 SEP 1895

Date of writing Report Sept 16<sup>th</sup> 1895 When handed in at Local Office 18 Port of Glasgow  
 No. in Reg. Book 338 Survey held at Looon Date, First Survey 13<sup>th</sup> Sept Last Survey 13<sup>th</sup> Sept 1895  
on the Machinery of the Wood, Iron or Steel S.S. "Marlay" Master W. M. Clark  
 Tonnage Gross 448 Net 349 Vessel built at Belfast By whom W. M. Clark When 1890-9  
 Registered Horse Power 170 Engines made at " Owners R. Redcastle & Co Port Dublin Voyage "  
 No. of Main Boilers 2 No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Dry Dock  
 Steam Pressure in Main Boilers 90 lb. in Donkey Boilers 90 lb. (State name of Dock.) Looon

Last Survey No. 3740 Port Glasgow  
 Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including use of N.B., if any).
<u>+100 A.1.</u> <u>4/95-</u> <u>ssho. 1-94</u>		<u>+L.M.C.</u> <u>10/94</u>

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If the Survey is not complete state what arrangements have been made for its completion?

Propeller shaft drawn and examined, also stem tube, bushes, etc. Sea connect. Overhauled, Cylinders, pistons & slide valves etc.  
(See Glasgow Report N° 13206)

(See Lunnet List)

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 4,04, B.&N.S. 4,04 or L.M.C. 4,04, 140 lb., F.D., &c.)

The propeller shaft & other portions of machinery mentioned above are in good condition and as far as seen the machinery of this vessel is eligible in my opinion to remain as classed

Office of Registration Fee (per Sec. 27) £ : :  
 Survey Fee (per Section 28) £ : :  
 Special Damage Fee (per Section 28) £ : :  
 Travelling Expenses (if chargeable) £ " : :  
 Fees applied for  
16/9/95  
 Received by me,  
18/9/95

James Morrison  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\* State if Certificate is required.

Committee's Minute

Assigned

as now  
but without limit

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

\* Certificate to be sent to

16-LRPH-Report No. 9-Transfer Ink-5,000, 3/4/95.



Lloyd's Register Foundation

GLS 173-0079



It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

13945. 99  
Vessel's name to be removed  
from Limitation List

Per  
19.9.96

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation