

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office)

THUR, 18 NOV 1897

Date of writing Report *17<sup>th</sup> Nov* 18 *97* When handed in at Local Office *18* Port of *Glasgow*  
 No. in Reg. Book. *180* Survey held at *Glasgow* Date, First Survey *4<sup>th</sup> Nov* Last Survey *5<sup>th</sup> Nov* 18 *97*  
 on the Machinery of the *Wood, Iron or Steel* *SS "Victoria"* (No. of Visits *2*)  
 Tonnage { Gross *1620* Vessel built at *Glasgow* By whom *A. Stephen & Sons* When *1884-10*  
 Net *1022* Engines made at *do* When *1887* Boilers, when made (Main) *1887* (Donkey) *1887*  
 Registered Horse Power *148* Owners *MacLay & Co. Antyre* Port *Glasgow* Voyage *Bilbao*  
 No. of Main Boilers *1* If Surveyed *Afloat* in Dry Dock *Govan*  
 Steam Pressure in Main Boilers *160 lb* (State name of Dock.)  
 in Donkey Boilers *75 lb*

Last Survey No. Port

Particulars of Examination and Repairs (if any) *Damage*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

When in dry dock the vessel's propeller fastenings, & sea connections were examined, and found in good order. The propeller shaft drawn & examined, & found in good condition, now refitted, shaft down 18".

Damage stated to have been sustained this vessel grounding at La Rochelle on 18.10.97, voyage Swansea to La Rochelle.

General Observations, Opinion, and Recommendation:— *The machinery of this vessel*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.95, B.&M.S. 9.95 or L.M.C. 9.95, 140 lb., F.D., &c.)

as far as seen, is in a good & safe working condition, and, in my opinion, is eligible to remain as classed, without fresh record of survey.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
	£	:	:	Received by me, 18

\*State if Certificate is required

Committee's Minute

FRI, 19 NOV 1897

Assigned *As now*

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register

Foundation

GLS179-0343



Plans shaft & sea connections exam<sup>d</sup>.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

10/11/97

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation