



Leaves shaft removed on acc of crew  
stem broken partly rotted

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

Vessel name to be removed  
from class list

*[Signature]*  
2/1/98

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Lined area for surveyor's report.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation