

© 2020
Lloyd's Register
Foundation

16414 Gls

and a few other deck fittings of a minor importance
made good

The upper part of bunkers have been cleaned
and recoated

H. W.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register
Foundation