

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office TUES, 1 NOV 1898)

Date of writing Report *1st Oct 1898* When handed in at Local Office *1st Oct 1898* Port of *Glasgow*  
 No. in Reg. Book *189* Survey held at *Glasgow* Date, First Survey *and* Last Survey *21 Oct 1898*  
*on the Machinery of the Wood, Iron or Steel SS Victoria* Master *J P Turner*  
 Tonnage { Gross *1620* Net *1022* Vessel built at *Glasgow* By whom *A Stephen & Son* When *1897* 10  
 Registered Horse Power *148* Engines made at *Glasgow* When *1887* Boilers, when made (Main) *1887* (Donkey) *1887*  
 No. of Main Boilers *1* Owners *SS Victoria Co Ltd* Port *Glasgow* Voyage *Bordeaux*  
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
 Steam Pressure in Main Boilers *160* in Donkey Boilers *70*

Last Survey No. Port

Particulars of Examination and Repairs (if any) *Docking*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*Do. " Donkey " *No*If this was not done, state for what reasons? *Not due for survey.*

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? *No*At what pressure were they afterwards adjusted under steam? *✓*Did the Surveyor examine the Safety Valves of Donkey Boiler? *No*To what pressure were they afterwards adjusted? *✓*Has the propeller shaft been drawn and examined at this time? *No*If spare propeller shaft fitted, state whether new? *✓*State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? *3 1/2" bare*If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *Complete*

*When this vessel was in dry dock the propeller and sea cock fastenings were examined and found in good condition*

*The propeller shaft was last run Nov 1897. See Ch report 15625.*

General Observations, Opinion, and Recommendation:— *The machinery of this*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., F.D., &c.)

*vessel so far as seen, is in good condition and is eligible in my opinion to remain as classed in register book.*

Office or Registration Fee (per Sec. 27)..... £ : : Fees applied for  
 Survey Fee per Section 28)..... £ : : 18  
 Special Damage Fee (per Section 28)..... £ : :  
 Travelling Expenses (if chargeable)..... £ : :  
 Received by me, 18

State if Certificate is required

Committee's Minute

FRI, 4 NOV 1898

Assigned *as now*

*George Murdoch.*  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Lloyd's Register  
 Foundation

6-15182-0173

Has a Survey also been held on Ship?  
 If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

\*Certificate to be sent to



*It is submitted that  
this vessel is eligible to  
remain as CLASSED.*

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*A.C.A.*

*1. 11. 98.*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register  
Foundation