

S. S. "Lady Martin" Glasgow Report No 8899.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

No. 8044

(Received at London Office)



TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by Messrs D Colville & Sons of Glasgow for Boiler No. 87 to be constructed by Messrs Dunsmuir & Jackson of Glasgow for Messrs Workman Clark & Co's S.S. No 60

Date first visit June 29th 1888 last visit July 3rd 1888 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Back Tube Plate	L501		6234	.96	1.40	1344	37.64	28.0	29.5	

W.P.
11/7/88

Fee £ : :
Expenses £ : :
£ : : To be paid by

© 2021
H. N. Dove
Surveyor, Lloyd's Register
Glasgow