


S.S. "Lady Martin" Glasgow Report No. 8899.  
 LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 8127

(Received at London Office)



**TESTS OF BOILER STEEL.**

Tests of 1 Steel Plate manufactured by Messrs D. Colville Sons of Motherwell for Boiler No 87 to be constructed by Messrs Dunsen & Jackson of Glasgow for Messrs Workman Clark & Co's S.S. No. 60

Date first visit July 10<sup>th</sup> 1888 last visit July 13<sup>th</sup> 1888 No. of visits

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to \_\_\_\_\_ samples as set forth below, and the temper and bending tests to a shearing from the plate with satisfactory results

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	End Tube Plate	G644		1149	.83	2.13	1.768	50.78	28.7	24.52	

*M*  
16.7.88

HILLING

Fee ..... £ : :  
 Expenses £ : :  
 £ : :

To be paid by



© 2021

*H. M. Dove*

Surveyor, Lloyd's Register.

*Glasgow*  
13.7.88

GLS212-0036