

Ship
"Albert Victor"

Extract from Mr. Martin's Report
dated August, 1864.

Called attention to some trenails in
bottom wrongly placed, they being too near, or too
far from the edges of Planking; Also called
attention to some sawn trenails lying on the
ground, not good in quality, recommended that
such trenails be not driven. This appears to be
a good ship such as these builders are celebrated
for. =

GRK 295-0080