

Serius Greenock 12621

Before dealing with this case it is submitted that the surveyor be requested to state "If steam from main boilers can enter the donkey boiler, as no mention of this appears on the reports":

Dr to Lynk
16/3/00

Dr to M.D.
16/3/00

A.S.
16.3.00

© 2020



Lloyd's Register
Foundation

GRK350-0162

each boiler

Material

Length of plain part	top bottom	Thickness of plates	crown bottom	Description of longitudinal joint	No. of
Working pressure of furnace by the rules		Combustion chamber plates: Material		Thickness: Sides	Back