

REPAIRS OR EXAMINATION AS PER RULE, FORM

2nd Survey Vessel placed on lib. bottom cleaned examined & repaired

2m, 9.9.

1

Sent to Chief Surveyors

25/11/09

Received from Chief Surveyors

VESSEL'S NAME

Inv. S. S. "Thursby"

Report

Gntk.

No. 15680.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

2nd Survey (3rd Series) When due

11-08

Noted.

RH

25/11/09



© 2019

Lloyd's Register Foundation

ARK356-0149

Outside Plating

(State which.)  
Rudder

Caulking  
Caulking

WOOD VESSELS  
ditto

Sails

Equipment, la