

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokenout plates

Yes.

It is submitted that
The Surveyor be requested to state whether
the blow off Cocks are fitted with a spigot
and brass covering plate.

A.C.H.

9. 1. 99



Lloyd's Register
Foundation

HPL 383-0172

Length of plain part bottom { 42" Thickness of plates bottom { 3/32 Description of longitudinal joint welded