

Dimitrios N. Pallas

F.E.

Received by Chief Surveyor 15. 6. 99

Received from Chief Surveyor

NAME *See S.S. "Daltonhall"* Report *Spl.* No. *10894*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report 24/5/92.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	<i>3/20"</i>	<i>Proportions</i>
Description of Framing:— <i>Deep (Bath angle) framing, sectional (viz., ordinary, deep, zed, channel or bulb-angle), area in excess of Rules.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\dagger$  100 A 1 ("Steel") "Spar Deck" as recommended.

$\dagger$  100 A 1 ("Steel") "Spar Deck"

1 DR (Stl) & Spar DR (Stl) & deep framing.

W. B = Cell DB a 106' in E & B 40' f 144' 732 E FPT 926 APT 276

FK 6BH Cam. AYCP.

*C. H. J.*  
15/6/99



© 2019

Lloyd's Register Foundation

HPL385-0117

age space  
In tween Deck, size and spacing  
Hold

Angle on ditto  
Tie Plates  
Deck Material and thickness