



© 2020

Lloyd's Register  
Foundation



s.s. "Clam".

General view of repairs wood

See plan for details bottom damage.

HPL387-0140 (1/2)