

Hull Feb 29/84
C H Wilson Esq. M P
30 Grosvenor Square
London

Sir

The S. S. "Rosario" has had a very heavy passage both out and home. and there is a quantity of cargo damaged especially in No 2 hold. Mr. McNeill, Lloyd's Surveyor Mr. Cole Capt Butler and myself. have examined all the holds - and find two butts on each side in Sheer Strake. front of poop started and a quantity of water has come through them. there are four butts in the iron deck. started also aug bar each end of No 2 hatchway. there are three butts in No 3 hold and two in after hold leaking. The poop deck is leaking in several places Mr. Cole is going to send men to Calk it.

"Orlando" is now in Humphreys Graving dock. there are 150 loose rivets to renew in the after bul plate inner post and fish plate. also part of the bulge keel is broken. we are renewing the Shortest pieces there are four about 6 ft in length.

Yours Obediently

W. J. Maclean

1884

3 March

S.S. Rosario.

WZ



© 2020

Lloyd's Register
Foundation