

ed pumps one Diameter of ditto 2 3/8 Stroke 13 Can one be overhauled while at work

## S. S. Monarch

It is submitted that this Report be returned to the Surveyor & he should be asked to explain how it is that these engines have cylinders 15" x 34" dia. & tunnel shaft 5 3/8" dia. whereas the engines mentioned on his Report h<sup>o</sup> 9715, & said to be the same, have cylinders 16" x 33" dia & tunnel shaft 5 3/4" dia.

He should state clearly whether the engines & boilers now fitted in the steam trawler "Monarch" have been in use at any time before being fitted on board this vessel & whether he has examined the main boiler at this time to satisfy himself that no deterioration has taken place.

Rr to Hull  
19/8/96

app<sup>d</sup> Mr. J. R.

J. E. S.  
©19.8196

Lloyd's Register  
Foundation

100413-0024

of stays one Thickness 1 1/2 Pitch of stays 1 1/2 How are stays secured all nuts Working pressure by rules 126