

deck new. The deck plating and casings on starboard side in way of boiler opening removed and afterwards replaced, and 2 spar deck plates and 2 coaming plates new. The donkey boiler seating new.

On starboard side, 1200 ft. of $3\frac{1}{2}$ " $\frac{1}{4}$ " pin main deck, and 1100 ft. of teak spar deck, new.

The bottom cleaned, examined, and recoated. The rudder pintles rebushed.

J. Thomson