

(97) Change of Owners 140
REPORT of SURVEY for REPAIRS.

No. 423
on the *SS John Laird* Master *Case*
Survey held at *London* Date *27th* 184*8*
Tonnage *270* Built at *Spain* When built *1842*
By whom built *Laird* Owners *Jughe Smith*
Port belonging to *London* Destined Voyage *China*
If Surveyed Afloat or in Dry Dock *At Docks*

Last Survey, No. *13960* Classed *A1*
Port *London* Built of *Iron*

REPAIRS

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <i>Good</i>	Timbers of the Frame <i>Good</i>	Masts, Yards, &c. <i>Efficient</i>
Lower Deck Beams & Fastenings <i>Efficient</i>	Keelsons <i>Efficient</i>	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

*Is in good and efficient condition
and may remain as classed*
How long

The Amount of Fee.....£ / : is received by me.

Certificate (if required)

Committee's Minute

Character assigned

29th Feb 1848



© 2019

Lloyd's Register
Foundation

IRON430-0103