

REPORT of SURVEY for REPAIRS.

Recd 6/9/58

No. 1481 Survey held at Glasgow Date 28th May 1858
 on the Ship "Evelina" Master Donald M. Lachlan
 Tonnage 247 Built at Dumbarton When built 1855
 By whom built Alex. Gentry Owners John Walker
 Port belonging to Glasgow Destined Voyage Puerto Ayres
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 1267 Port Glasgow Classed 9 A

REPAIRS

Of Damage, Renewed Fifty Six Feet of Top Gallant Rail and Thirty Three Feet of Bulwarks on each side and One Hundred and Four Feet of Lining and cladding to Bulwarks, Five feet of Iron Bulwarks Fished the Foremast Head, New Five Top Mast and Pillar Starboard Cut Head repaired, Brackets and Chocks to Davits renewed some new Sails and Spars

Present Condition of the

Decks	<u>Good</u>	Keelsons	<u>Where seen Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>Not seen</u>	Pumps	<u>3 in No. Metal do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>2 in do do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame	<u>Where seen Good</u>	Masts, Yards, &c.	<u>Part New & Good</u>
Lower Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>do do</u>	Sails	<u>do do</u>
Planksheers	<u>do</u>	Clamps and Shelves	<u>do do</u>	Anchors	<u>No. of 3 1/2 in Iron Wedge</u>
Sheerstrakes	<u>Plating Where seen Good</u>	Ceiling	<u>do do</u>	Cables	<u>Complete & Good</u>
Topsides	<u>do do</u>	Rudder	<u>do do</u>	Hawsers and Warps	<u>do do</u>
Wales	<u>do do</u>	Copper	<u>When put on</u>	Standing & Running Rigging	<u>do do</u>
Plank (Bottom) and Counter	<u>do do</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

This vessel is now in a good and efficient condition fit for the safe conveyance of Dry and Stowable Cargo to and from all parts of the World and may continue as afloat

The Amount of Fee.....£ : 10 : - is received by me,

Special Damages £ : 4 : - Paid Sept 4/58

Certificate (if required) : : -

Committee's Minute 7th September 1858

Character assigned 9 A



© 2019

Lloyd's Register
 Foundation
 IRON 433-0304