

REPORT of SURVEY for REPAIRS.

No. 179 Survey held at London Date Aug 10th 1858
 on the S.S. Gibraltar Master W. G. Hall
 Tonnage 983 Built at London When built 1834
 By whom built _____ Owners Sp. & Pri. Stm. Co. Comp.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 1509 Port Iron Classed A

REPAIRS

Now done, Plank sheen, waterway, and one beam of deck
 each side caulked, the bottom scraped and coated
 with Red Lead, the outside coat with Naptha and Black
 Varnish. Two pieces of plate, one each side shifted, being
 basted around the Blow off pipes.

Caused some ceiling to be lifted, and examined
 the rivets and plates which proved satisfactory.

Present Condition of the

Decks <u>Good</u>	Treeails _____	Windlass and Capstan _____
Waterways <u>Caulked</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>Good</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings } <u>firm</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons <u>Good</u>	Sails <u>supp.</u>
Plank sheers _____	Clamps and Sticks _____	Anchors No. of _____
Sheerstrakes } <u>Good</u>	Ceiling _____	Cables _____
Topsides } <u>Good</u>	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Painted</u>	When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She is fit, in my opinion, to continue classed A. 1.

W. W. W. W. W.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : if

Certificate (if required) : :

Committee's Minute 21st September 1858

Character assigned A



© 2019

Lloyd's Register
 Foundation