

2247

REPORT of SURVEY for REPAIRS.

Ru 1/10/60

No. 2060 Survey held at West Hartlepool Date 30 July 1860
 on the Iron Screw Steamer "Admiral Boscawen" Master J. P. Paxton
 Tonnage 311 2/2 Built at Glasgow When built 1857
 By whom built _____ Owners West Hartlepool, Iron, & Co.
 Port belonging to West Hartlepool Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock In Pile Ho dock

Last Survey, No. 2020 Port Iron Classed G A S

REPAIRS Thro. damage, two plates taken out of starboard bow, rolled & refitted, two frames new at upper parts, Bottom scraped clean & coated with two coats of red paint.

Present Condition of the

Decks	<u>Efficient</u>	Rivets	<u>Efficient</u>	Windlass and Capstan	<u>Efficient</u>
Waterways	<u>Good & Efficient</u>	Breasthooks and Stems	<u>Good & Efficient</u>	Pumps	<u>Efficient</u>
Comings	<u>Good & Efficient</u>	Transoms, Pointers, and Crutches	<u>Good & Efficient</u>	Boats	<u>Efficient</u>
Upper Deck Beams & Fastenings	<u>Good & Efficient</u>	Timbers of the Frame	<u>Good & Efficient</u>	Masts, Yards, &c.	<u>Efficient</u>
Lower Deck Beams & Fastenings	<u>Good & Efficient</u>	Keelsons	<u>Good & Efficient</u>	Sails	<u>Efficient</u>
Planksheers	<u>Good & Efficient</u>	Clamps and Shelves	<u>Good & Efficient</u>	Anchors No. of	<u>Efficient</u>
Sheerstrakes	<u>Good & Efficient</u>	Ceiling	<u>Good & Efficient</u>	Cables	<u>Efficient</u>
Topsides	<u>Good & Efficient</u>	Rudder	<u>Good & Efficient</u>	Hawsers and Warps	<u>Efficient</u>
Wales	<u>Good & Efficient</u>	Copper	<u>Good & Efficient</u>	Standing & Running Rigging	<u>Efficient</u>
Plates (Bottom) and Counter	<u>Good & Efficient</u>	When put on	<u>Good & Efficient</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good

It is now in an efficient state, and may in our opinion remain as now classed G A S

The Amount of Fee.....£ 1 : 0 : 0 is received by me,


Special..... : : -

Certificate (if required) : : -

Committee's Minute 2nd October 1860

Character assigned G A S

record damage repair



© 2019

Lloyd's Register
Foundation

IRON434-0348