

2675

24425

REPORT of SURVEY for REPAIRS.

Iron

No. 186 on the S. S. Gibraltar of Iron Survey held at London Date Jan^y 2nd 18 62
 Master W. C. Hall
 Tonnage 985 Built at London When built 1854
 By whom built _____ Owners S. & P. S. S. Comp^y
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Union du dock

Last Survey, No. 2441 Port Iron Classed 6 A 1
 Cont 60 — 3 61

REPAIRS

In consequence of Damage, see Special Report,
 the fore keel repaired by a shoe piece worked
 under it and the keel rivets from the keel of
 foremast forward renewed —

Present Condition of the

Decks	Greenails Rivets	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank ^{ing} (Bottom) and Counter		

General Observations and Opinion, *Good where seen* Caulking of Bottom, Deck, & Waterways. *good where seen*

This vessel is now in good condition and is eligible
 in my opinion to remain classed A 1

The Amount of Fee.....£ _____ is received by me,

Special damage 2 : 2 : — *W. C. Hall*

Certificate (if required) _____

Committee's Minute 4th February 1862

Character assigned Cont 3 A 1 *W. C. Hall*



© 2019

Lloyd's Register
Foundation

IRON 435-0296