

2862

27586

## REPORT of SURVEY for REPAIRS.

No.

899  
on the

Survey held at

London

Date

14<sup>th</sup> to 29<sup>th</sup> Mar 1862  
7 April

Tonnage

549  
421

Built at

London

When built

1854

By whom built

Owners

Bake Adam &amp; Co

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Lunghy dry dock Deptford Deptford Creek

Last Survey, No.

2002

Port

Iron.

Classed

6 A \ Capred

## REPAIRS

Survey requested for reclassing. found the bottom newly coated, no stapes made for the inner or outer surfaces of plating cleansed for examination. Engines and boilers removed and some portions of the ceiling. but the hold was much lumbered and no preparations made for our survey. the ship's husband informed us that no time should be given when ready, but we find no preparation for survey and new engines & boilers are being fitted without an opportunity afforded to examine her in way thereof

1<sup>st</sup> April, owners decline the survey

## Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing &amp; Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, &amp; Waterways.

The owners having declined the survey we are unable to recommend her for Classification

The Amount of Fee.....£ : : is received by me,

Special..... / : / : -

Certificate (if required) : :

Committee's Minute

8<sup>th</sup> April 1862

Character assigned

Refused

Wm L. Darcy

J. C. Martin



© 2019

Lloyd's Register  
Foundation

IRON435-0463

Mar. 2. 4. 62