

3428

REPORT of SURVEY for REPAIRS.

No. 2330 Survey held at West Hartlepool Date 9th Decr 1863
 on the "Admiral Cator" Master _____
 Tonnage 311 Built at Glasgow When built 1857
 By whom built 212 Owners W. H. L. S. M. Co.
 Port belonging to West Hartlepool Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock In Pile Space & Dock & Afloat

Last Survey, No. 2420 Port Iron Classed 9 A1

REPAIRS Now done ceiling lifted plating scraped clean inside & out excepting in way of asphalt (which appears all solid) four hold beams removed & two larger beams fitted in place of the same, with an angle iron on the inner edge of hold beam stringer plate $3 \times 3 \times 0/16$ & extra bracket knees fitted under the same, vessel coated outside & in with Black Varnish & paint, ceiling relaid, umallets unhung for cleaning. Engine repaired, a small deck house fitted abaft of engine room.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Is now in a good & efficient state and may in my opinion remain as now repaired 9 A1

The Amount of Fee.....£ 1 : 0 : 0 is received by me,

Special.....2 : 2 : 0

Det. 11/1 Certificate (if required) : :

Committee's Minute 1st January 1864

Character assigned 9 A1



© 2019

Lloyd's Register
Foundation

IRON437-0095