

3459

# REPORT of SURVEY for REPAIRS.

Re 5/2/64

No. <sup>340</sup> 26341 Survey held at West Hartlepool Date 23<sup>rd</sup> May 1864  
 on the "S.S. Duina" Master R. Leighton  
 Tonnage 123<sup>6</sup>/<sub>71</sub> Built at Sunderland When built 1862  
 By whom built Gowald Owners G. Fleming  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock In Pile Spence & Co. Dock

Last Survey, No. 2880 Port Iron Classed 9 A 1

REPAIRS, now done, seventeen keel rivets renewed, Stanchions fitted to main hatchway beams, outside plating scraped clean & coated over with two coats of paint.

Present Condition of the

Decks	<u>Good &amp; Efficient</u>	Trunnels <u>Rivets</u>	<u>Good &amp; Efficient</u>	Windlass and Capstan	<u>Good &amp; Efficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers		Keelsons		Anchor No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in a good & efficient state of repair and may in my opinion remain as now classed 9 A 1

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

S. P. Gladstone

Special..... : : -

Certificate (if required) : :

Committee's Minute 9<sup>th</sup> February 1864

Character assigned 9 A 1



© 2019

Lloyd's Register Foundation  
 1000437-0127