

3477

REPORT of SURVEY for REPAIRS.

No. 2346 Survey held at West Hartlepool Date 29 January 1864
 Supp. on the Screw Steamer "Harvest Queen" Master Nash
 Tonnage 562 Built at West Hartlepool When built 1860
 By whom built Pile Owners West Hill, Sten, & Co.
 Port belonging to West Hartlepool Destined Voyage Antwerp
 If Surveyed Afloat or in Dry Dock In Pile Spence & Co. Dock

Last Survey, No. 2346 Port Linn. Classed 6 A 1

REPAIRS Now done, Harbourside, one shell plate taken off & straightened & refitted, broken frame in way of the same repaired. Several rivets in keel & purliner renewed. Boilers taken out cement under & repaired & new boilers fitted, scraped clean inside & out excepting in way of ceiling & coated with paint & black varnish.

Present Condition of the

Decks	<i>Good & efficient where seen</i>	Treenails	<i>Good & efficient where seen</i>	Windlass and Capstan	<i>Winches good</i>
Waterways		Breasthooks and Stemson		Pumps	<i>Two & good</i>
Comings		Transoms, Pointers, and Crutches		Boats	<i>Three & good</i>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<i>Good</i>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	<i>Good & sufficient</i>
Planksheers		Keelsons		Anchors	No. of <i>3 Bowers 1 Kedge</i>
Sheerstrakes		Clamps and Shelves		Cables	<i>13/0 Good & sufficient</i>
Topsides		Ceiling		Hawsers and Warps	<i>No. 7. 5. 5. in. Good</i>
Wales		Rudder		Standing & Running Rigging	<i>Good</i>
Deck (Bottom) and Counter		Copper		When put on	

General Observations and Opinion.

Caulking of Bottom, Deck, & Waterways. *Good*

Is now in a good & efficient state of repair and may in my opinion remain as now classed 6 A 1

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

Special..... / : / : 0

Certificate (if required) : :

Committee's Minute 23rd February 1864

Character assigned 6 A 1

second damage repairs



© 2019

Lloyd's Register
F00437-0146