

REPORT of SURVEY for REPAIRS.

No. in Book. *No. 9509* Survey held at *E Shields* Date *18th Nov to 26th Dec 1864*
 on the *Iron S. "Leila"* Master *C. A Fairburn*
late "City of London"
 Tonnage *1381* Built at *Stockton* When built *1864*
 By whom built *Richardson & Duck* Owners *Stuart & Douglas*
 Port belonging to *Liverpool* Destined Voyage *Calcutta*
 If Surveyed Afloat or in Dry Dock *J & W Smith's dry dock*

Last Survey, No. *3758* Port *Liverpool* Classed *12 A 1*
9.64

REPAIRS

Bottom coated with Peacock's composition
 3 Carps Pk cut. 2 on the Starboard side and 1 on the Port side
 above Ports a clamp plate 16" x 7/16" introduced extending 3
 spaces afore & abaft Port and connected to outside plating
 by angle iron forming a 7

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchor No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Survey held to see Carps Pk properly arranged so as not to diminish her strength & in charge of owners -

The Amount of Fee.....£ / :- : - is received by me,

Special..... - : - : -

Certificate (if required) - : -

Committee's Minute *3rd January 1865*

Character assigned *12 D 1*



© 2019

Lloyd's Register Foundation

IRON 438-0064