

REPORT of SURVEY for REPAIRS.

No. 19326 Survey held at Birkenhead Date Feb 28th March 13th 1865
 on the (Mm) SS "Gladiator" Master J. Guard
 Tonnage 591 Built at Stocnton When built 1849
 By whom built Pearse Owners J & S Harrison
 Port belonging to Liverpool Destined Voyage Pernambuco
 If Surveyed Afloat or in Dry Dock Great Heat graving & Collingwood dock

Last Survey, No. 2827 Port Iron. Classed 9 A 1
 REPAIRS

The bottom scraped & coated with Composition.
 the ceiling removed in places - found the surfaces of iron
 & cement in good condition except in Engine room where
 the cement was part defective but has been renewed.
 Windlass unhung & linings taken off found good
 and the solid bulwarks around both quarters renewed
 of A oak.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Satisfactory

Is now in an efficient condition & fit for the
 conveyance of dry & perishable cargoes to & from all parts
 of the world & in my opinion eligible to remain as Classed, &

The Amount of Fee.....£ 1 : : : is received by me, marked to 1865.

Special..... 2 : 2 : " 6/4/65

Certificate (if required) " : " : "

Committee's Minute Liverpool, 7th April, 1865

Character assigned 9 A 1 - (2.5.65)

of second owners



Lloyd's Register
 Foundation
 IRON438-0208

Gladiator

~~19362~~

19326

H



© 2019

Lloyd's Register
Foundation