

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **540** No. **1218** Survey held at **Falmouth** Date **April 18th 1865**
 on the **S. S. Andalusia** Master **Duncan**
 Tonnage **274** Built at **Swan** When built **1863**
 By whom built **Swan** Owners **Morres & Co**
 Port belonging to **Glasgow** Destined Voyage **Mediterranean**
 If Surveyed Afloat or in Dry Dock **Afloat**

Last Survey, No. **3417** Port **Glasgow** Classified **g A 1**

REPAIRS

This vessel put in here damaged by collision with Spanish Steamer Sofia. The upper part of Stem was badly twisted the Bulwark plates on both sides of Bow and ~~three~~ the Fore Hoods of three upper courses of plating on Port side and fore hoods of two upper courses on Starboard side were started and fractured one of the ^{Bow} frames broken on Port side and Rails Bow blocks &c all stove. She has had new upper part of Stem new fore hoods and Bulwark plates on both sides and broken frame scarfed and properly secured and all damages & defects whatever made good

Present Condition of the

Decks	Good	Treenails	—	Windlass and Capstan	Good
Waterways	Do	Breasthooks and Stemson	—	Pumps	Do
Comings	Do	Transoms, Pointers, and Crutches	—	Boats	Do
Upper Deck Beams & Fastenings	Not seen	Timbers of the Frame at the openings	—	Masts, Yards, &c.	Do
Lower Deck Beams & Fastenings	Do	Ditto Ditto at other places	—	Sails	Do
Planksheers	Good	Keelsons	—	Anchors No. of	As per rule
Sheerstrakes	Do	Clamps and Shelves	—	Cables	Do
Topsides	Do	Ceiling	—	Hawsers and Warps	Do
Rails	Unseen	Rudder	Good	Standing & Running Rigging	Good
Plank (Bottom) and Counter	Do	Copper	— When put on —		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **Good**
 This is a good vessel has had all damage made good and is in my opinion well worthy to retain her present character

F. N. Thomas
 Surveyor

The Amount of Fee.....£ : 10 : 0 is received by me,

Special..... : :

Certificate (if required) : 5 : 0

Committee's Minute **21st April** 18 **65**

Character assigned **GA 1**

record damage repairs



© 2019

Lloyd's Register Foundation

1RON438-0221