

4087 Dr.

set fair and riveted. fifteen bracket-knees added to the
hold beam ends where the former knees were broken in riveting.
The wood waterways scraped bright. The deck dressed fair.
Several planks renewed and the whole refastened with steel
and nut bolts and caulked. The Handlass stripped and
found good. The chain cables found sufficient.

The Vessel has now had new boilers and boiler heaters.
and the plating. &c has been painted inside and out.

H. Munro
W. H. Turner.

Albanian
19378-



© 2019

Lloyd's Register
Foundation