

5102

REPORT of SURVEY for REPAIRS.*Change of owners**Rev 18/10/66*No. in Reg. Book. **No. 3693** Survey held at *Hull* Date *October 8th* 18*66*on the *Iron Steamer "Baron Hambro"* Master *Hanshaw*Tonnage *494* Built at *London* When built *1861*By whom built *Langleigh* Owners *Thos. Wilson Sons & Co.*Port belonging to *Hull* Destined VoyageIf Surveyed Afloat or in Dry Dock *at C. W. Gales Slip-way & Afloat in Victoria & Princess St. B.*Last Survey, No. *4090* Port *Iron.* Classed *9 A 1**(8864) 4.65*

REPAIRS

Now done The outside plating scraped bright and coated with Paint New Supellor fitted

Present Condition of the

Decks	Treenails <i>Rich.</i>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <i>3 1/2</i>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

*Is eligible in my opinion to remain as classed A 1*The Amount of Fee.....£ *1* : - : is received by me, *M. Davidson*

Special.....

Certificate (if required).....

Committee's Minute *19th October 1866*Character assigned *9 A 1*

© 2019

Lloyd's Register
Foundation

IRON440-0112