

5927  
**ANNUAL SURVEYS.**

~~28844~~

Recd. 19.12.67

No. 592 Survey held at London Date Decr 13th 18 67  
on the S.S. "Lorena" Master \_\_\_\_\_  
Tonnage 794 Built at Stockton When built 1862  
By whom built Richardson Owners Anglo Ionian S. N. Co  
Port belonging to London Destined Voyage Mediterranean  
If Surveyed Afloat or in Dry Dock On Pontons Victoria Dock

Last Survey, No. 5092 Port of Iron Classed 9A1  
2.5.65 9.66

The present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do <u>at other places</u> _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>1B, 1S, 2K</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper <u>✓</u> When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Painted bottom with three coats of composition paint.  
Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 20th Decr 18 67  
Character assigned 9A1 M.A.S.

*John Maxwell*

Certificate (if required)

No. 5002 Survey held at London Date Decr 13th 18 67  
on the S.S. "Henry Morton" Master J. Douglas  
Tonnage 986 Built at Newcastle When built 1860  
By whom built Palmer Owners Jerry & Son  
Port belonging to London Destined Voyage Coasting  
If Surveyed Afloat or in Dry Dock on Pontons Victoria Dock

Last Survey, No. 5002 Port of Iron Classed 6A1  
Cont 66. 3. 6.66

The present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>at the Openings</u> _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Do Do <u>at other places</u> _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>1B, 1S, 2K</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper <u>✓</u> When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Painted bottom with two coats of red and white lead and one of tallow; caulked several butts of plating & unshipped & repaired rudder.

Is now in good and efficient condition and in my opinion eligible to remain as classed

Committee's Minute 20th December 18 67  
Character assigned Cont 3A1 M.A.S.

*John Maxwell*

Certificate (if required).

IRON44-0380