

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 9502** Survey held at Sunderland Date Nov. 30/68 to Jan. 6th 1869
 91 on the Iron Ship James Mathart Master Buchanan
 Tonnage 776 built at Leith When built 1864
 By whom built Morton Owners Thompson & Co.
 Port belonging to Leith Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 5070 Port London Classed A 1, 66

REPAIRS

At the present time, nearly all the fixed ceiling removed from the timbers upwards and examined and found good, part of the cement being worn off. The bottom has been newly cemented and coated with Red Paint above ditto.

Present Condition of the

Decks	Treenails <u>Revised</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stenson	Pumps <u>"</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>"</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings <u>Good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>"</u>
Planksheers	Keelsons	Sails <u>Well found</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 Bts. 12 & 14 lbs</u>
Topsides	Ceiling	Cables <u>Complete</u>
Wales	Rudder	Hawsers and Warps <u>Sufficient</u>
Plank (Bottom) and Counter	Copper <u>When put on</u>	Standing & Running Rigging <u>Good</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in an efficient state and in my opinion entitled to remain as classed & marked "S.S. M. 1, 69"

Leithhouse Martindale

The Amount of Fee.....£ " : " : " is received by me,

Special..... 2 : 2 : "

Certificate (if required) " : " : "

Committee's Minute 22nd January 1869

Character assigned

A 1 S.S. M. 1-69



© 2019

Lloyd's Register

IRON 443-0284