

7351

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 9691** Survey held at Sunderland Date August 20<sup>th</sup> to 21<sup>st</sup> 1869  
272 on the hull of "Biddick" Master H. M. Toose  
Tonnage 540 built at Sunderland When built 1864  
By whom built Sains Owners H. M. Toose  
Port belonging to Sunderland Destined Voyage France  
☒ Surveyed Afloat or in Dry Dock Commissioner's

Last Survey, No. 3861 Port London Classified A. 1 11-64

REPAIRS done and Survey No. 2. The timber, beams and ceiling equal to these strikes both sides removed and both surfaces of outside plating exposed - man-holes to double bottom in each hold removed and cement phase exposed to view found to be in a good and satisfactory condition. - Planks cleared and the oxidation removed from the frames, stringers, beams and bulkheads. Fitted a cedar plate under Fire Hatch on top of main keelson 15 ft x 4 ft x 1/2 in. Repaired the outside surface of the iron work.

## Present Condition of the

Decks	Treenails <u>Planks</u>	Windlass and Capstan <u>Complete</u>
Waterways	Breasthooks and Stems	Pumps <u>as found</u>
Comings	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>3 h.c.</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>as found</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>by</u>
Planksheers	Keelsons <u>planks</u>	Sails <u>as found</u>
Sheerstrakes <u>Plating</u>	Clamps and Shelves	Anchors No. of <u>3 h. 10. + 2 k</u>
Topsides	Ceiling <u>as found</u>	Cables <u>240 fathoms Complete</u>
Wales	Rudder	Hawsers and Warps <u>as found</u>
Plank (Bottom) and Counter	Copper <u>as found</u> When put on <u>as found</u>	Standing & Running Rigging <u>as found</u>

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good phase examined

This vessel appears in good and efficient condition, and in my opinion eligible to remain A. 1 as classed S. S. No. 2 - 1869

The Amount of Fee.....£ : : is received by me.

Special..... 3 : 3 :

Certificate (if required) : 5 :

Committee's Minute 14<sup>th</sup> September 1869

Character assigned

(S.S. No. 2. 69)  
M. C.



© 2019  
Lloyd's Register  
Foundation

IRON444-0399



7351 Iron

with one coat of Zinc paint and two antirust  
sprays to bulkheads overhauled, likewise  
the deck pumps.

Chain cables painted on deck and found

complete

Engines overhauled *P. J. Lake*

and Certificate

appended

*B*



© 2019

Lloyd's Register  
Foundation