

7622  
Damage Repairs

# REPORT of SURVEY for REPAIRS.

Rec'd 11/10/68

No. in Reg. Book. **No. 9708** Survey held at Sunderland Date June 7<sup>th</sup> to 12<sup>th</sup> 1868  
 on the Iron S.S. William Hunter Master J. Bowle  
 Tonnage 767 built at Newcastle When built 1865 - 2mo  
 By whom built Palmer Owners Hunter & Co.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

Survey, No. 6410 Port Droghda Classed A1-68, SS.N1-68  
 7.68

At the present time owing to damage.  
 Portside 3 bulged outside plate taken off and  
 put into the furnace & rolled fair & replaced.  
 4 Frames scarped & a few knee plates 2 lengths  
 of Bilge angle Iron & several rivets removed.  
 Part of the cement removed & the Bottom  
 coated with Paint

Present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan <u>SM</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails <u>Well found</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 Bore S. &amp; 1 Rods</u>
Topsides	Ceiling	Cables <u>Complete</u>
Wales	Rudder	Hawsers and Warps <u>Sufficient</u>
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging <u>Good</u>

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good

*Is now in an efficient state and in my  
 opinion entitled to remain as classed.*

*Senhouse Mastermade*

The Amount of Fee.....£ 2 : " : " is received by me,

Special..... 2 : 2 : "

Certificate (if required) , : " : "

Committee's Minute 12<sup>th</sup> October 1869

Character assigned A1

*record damage repairs*



© 2019

Lloyd's Register  
 Foundation

IRON45-0033