

REPORT of SURVEY for REPAIRS.

Recd 4/10/69

No. in Reg. Book. **No. 2117** Survey held at **21/10/69** Date, first Survey **17 Sept 65** Last Survey **22 Sept 1869**
 on the **Screw S.S. Alexandria** Master **Partridge**
 Tonnage **813** built at **London** When built **1863**
 By whom built _____ Owners **London S.S. Ship Co.**
 Port belonging to **London** Destined Voyage _____
 If Surveyed Afloat or in Dry Dock **Afloat**

Last Survey, No. **7230** Port **Iron.** Classed **1 1/2**

REPAIRS, &c. This vessel put into Plymouth Sound with main hatches stove in the cross beam having broken in two. The hatchway being 12 ft long I suggested that there should be two cross beams and larger than the broken one which has been done and all made secure. A short piece of poop plank sheer on the S.W. side carried away has been made good. The lower plank of poop frame has been renewed and the deck caulked.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers	Cargo and Main Hatchways	Hatches

General Observations and Opinion,

The above damage having been properly repaired and no other thing visible she should in my opinion remain as classed.

The Amount of Entry Fee.....£ : : is received by me, in London.

Special..... 1 : 11 : 6

Certificate (if required) : :

Committee's Minute **29th October** 18**69**

Character assigned **1 1/2**



© 2019

Lloyd's Register
Foundation

IRON 445-0089