

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 157 Survey held at London Date August 20<sup>th</sup> 1870  
 on the S.S. + "Claine" (Iron) Master S. Bly  
 Tonnage 593 Built at Middlesbro When built 1864  
 By whom built \_\_\_\_\_ Owners Cory, Bros & Co  
 Port belonging to Cardiff Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Globe Ways & Limehouse dry dock  
 Last Survey, No. 8053 Port Iron Classed A 1  
 (S.S. Cls, No 2 - 70) 6.70

## REPAIRS

Now done in consequence of damage (see special Report).  
 The Stem, thirteen plates on Starboard and thirteen on port bow renewed also two Frames and the throat or breast plates of all stringers, five plates recoiled, four frames and one beam repaired also angle irons of stringers, Floor plates to two frames renewed, also one Hadose pipe and the forecastle deck.

## Present Condition of the

Decks		Freeboards	Rivets	Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	Sufficient
Planksheers	Good	Keelsons	Good	Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Riggings	
Plank (Bottom) and Counter		Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good and efficient condition and eligible in my opinion to remain classed A 1

The Amount of Fee.....£ 2 : - : is received by me,

Special.....

Certificate (if required) .....

Committee's Minute 16<sup>th</sup> September 1870.

Character assigned A 1

Spl damage 3.3.0 repor damage repair JBM



© 2019

Lloyd's Register Foundation

IRON447-0085