

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. 9965 Survey held at Sunderland Date, first Survey 30th Augst Last Survey 6th Sept 1870

on the S.S. "Damiatta" (Iron) Master Wright

Tonnage 565 built at Middlesbrough When built 1864 (6 460)

By whom built Backhouse Owners Cuthbertson & Co

Port belonging to Middlesbrough Destined Voyage London

If Surveyed Afloat or in Dry Dock In the River

Last Survey, No. 7765 Port Hartlepool Classed A 1 2.70 (S.S. 1-67)

REPAIRS, &c.

At present owing to Damage Renewed two upper Stern Plates & Angles Iron to ditto. Stern Waterway Stetlin Oak. Main Sail & Top Gallant on Stetlin Oak Solid Work at the Pitch Pine. 5 Top Gallant Stanchion at ditto Stetlin Oak. All the repair confined to the Stern.

a Third Brown Anchor Supplied 10.2.0 tested to 12.8.3.0 Certificate of Test issued from the "Weir" Testing House. & signed by Mr John Hartness.

Present Condition of the

Decks	Good when seen	Freemasts	Good when seen	Windlass and Capstan	Good
Waterways	OK	Breasthooks and Stemson	OK	Pumps	OK
Comings	OK	Transoms, Pointers, and Crutches	OK	Boats	OK
Upper Deck Beams & Fastenings	OK	Timbers of the Frame at the openings	OK	Masts, Yards, &c.	OK
Lower Deck Beams & Fastenings	OK	Ditto Ditto at other places	OK	Condition, how ascertained	OK
Planksheers	OK	Keelsons	OK	Sails	Well found
Sheerstrakes	OK	Clamps and Shelves	OK	Anchors No. of 3 Bra St & Red	
Topsides	OK	Ceiling	OK	Cables	Complete
Wales	OK	Rudder	OK	Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	OK	Copper	When put on	Standing & Running Rigging	Good
Engine Room Skylights	Good	Caulking of			
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		
Scuppers	Good				
Cargo and Main Hatchways	Good				
Hatches	Good				

General Observations and Opinion,

Is now in an efficient state and in my opinion entitled to remain as classed

The Amount of Entry Fee.....£ 2 : : : is received by me,

Special..... / : / : .

Certificate (if required) : : : .

Committee's Minute 28th October 1870

Character assigned

A

record damage repair



© 2019

Lloyd's Register Foundation

IRON447-0202