

16/4/11

ANNUAL SURVEYS.

No. 22764 Survey held at Liverpool. Date 13th 31 March 1871
 on the B. MARQUINESA Master A. De Witte
 Tonnage 282 Built at Hartlepool. When built 1869. 10mo
 By whom built Withey Owners De Witte & Co.
 Port belonging to Bilbao Destined Voyage Matanzas.
 If Surveyed Afloat or in Dry Dock Cunning Dry Dock

Last Survey, No. 7426 Port of Iron. Classed B. S. 10.69.

The present Condition of the

Decks	Ironails <u>Rocks.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1869.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom Scraped and painted. She is now in good condition. and in my opinion - is eligible to remain as classed.

Committee's Minute Liverpool 18th April 1871

Character assigned B. S.

Certificate (if required)

No. 252 Survey held at Liverpool. Date 13 March to 3 April 1871
 on the SHIP "RIVER NITH" Master Crawford.
 Tonnage 1126 Built at Newcastle. When built 1869. 4mo
 By whom built Schlenger Owners Hargrove & Co.
 Port belonging to Liverpool. Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Clayton Long Dock.

Last Survey, No. 7969 Port of Iron. Classed * A. S. 5.70

The present Condition of the

Decks	Ironails <u>Rocks.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1869.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom Scraped and painted - she is now in good condition. and in my opinion - is eligible to remain as classed.

Committee's Minute Liverpool 18th April 1871

Character assigned * A. S.

Certificate (if required).

IRON448-0268

"Marquinesa"
22.7.67
"River With"



© 2019

Lloyd's Register
Foundation