

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *No. 10135* Survey held at *Sunderland* Date, first Survey *1<sup>st</sup> May* Last Survey *15<sup>th</sup> May 1871*  
 on the Steamer "Frankland" Master *Bowles*  
 Tonnage *706* built at *Sunderland* When built *1869 (9 Aug)*  
 By whom built *James Laing* Owners *Morton*  
 Port belonging to *Sunderland* Destined Voyage *Hamburg*  
 If Surveyed Afloat or in Dry Dock *Cuttin's dry dock*

Last Survey, No. *8216* Original Report *9893* Port *Sunderland* Classed *90 A.I.*  
*8.70*

REPAIRS, &c. *Recomd. by club surveyors on acct. of damage*

*Now done*, The upper part of the stem renewed, scarphed at about the 9ft mark; 8 plates next stem on starboard side, & 7 do. on Port side, renewed; the four ends of stringer plates to deck & hold beams repaired and the angles renewed; the deck caulked, & the bottom painted.

## Present Condition of the

Decks	Ironails <i>Rivets</i>	Windlass and Capstan <i>Good</i>
Waterways	Breasthooks and Stemson	Pumps <i>Good</i>
Comings	Transoms, Pointers, and Crutches	Boats <i>3 W.</i>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <i>When seen</i>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <i>30.15.2K</i> <i>and</i>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plates (Bottom) and Counter	Copper Cement When put on <i>1869</i>	Standing & Running Rigging <i>Sufficient</i>
	Caulking of	
	Bottom, Deck, & Waterways <i>Good</i>	
Engine Room Skylights <i>Good</i>	Coal Bunker, Openings, Lids, &c. <i>Good</i>	Scuppers <i>Good</i>
General Observations and Opinion,	Cargo and Main Hatchways <i>Good</i>	Hatches <i>Good</i>

This vessel is now in good & efficient condition and eligible in my opinion to remain as classed 90 A.I.

The Amount of Entry Fee.....£ 2 : : : is received by me,

Special.....2 : 2 : -

Certificate (if required) : : : -

Committee's Minute *20<sup>th</sup> June* 18 *71*

Character assigned *90 A.I.*

*Record damage report*

*J.F.W.*



© 2019

Lloyd's Register Foundation

IRON448-0441