

REPORT of SURVEY for REPAIRS.

2990

No. in Reg. Book. **No. 2990** Survey held at West Hartlepool Date, first Survey 27th Sept Last Survey 4th Oct 1891
 on the S.S. "Farnley Hall" Master E. Fisher
 Tonnage 954 built at West Hartlepool When built 1891
 By whom built Swine & Co. Owners R. Swine
 Port belonging to West Hartlepool Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9134 Port Iron Classed 90 A1

REPAIRS, &c. Now done through damage (fire) Bridge deck on the Port side near Y. Pine also at fore part under chart house, Bridge deck caulked with part of main it.

Present Condition of the

Decks	Treenails <u>Reinforced</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>When put on</u>	Standing & Running Riggings
Engine Room Skylights <u>Good</u>	Caulking of	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	
General Observations and Opinion,	Scuppers <u>Good</u>	
	Cargo and Main Hatchways <u>Good</u>	

Is now in a good & efficient state, fit for the safe conveyance of perishable goods to & from all parts of the World or may in my opinion be now Classed 90 A1

The Amount of Entry Fee.....£ — : — : — is received by me, M. Gladstone

Damage Report Special..... 2 : 2 : —

Bel 1891 Certificate (if required) : — : —

Committee's Minute 10th October 1891

Character assigned 90 A1



© 2019

Lloyd's Register Foundation

IRON449-0323