

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 47 No. 358 Survey held at London Date, first Survey 25th Nov^r Last Survey Dec^r 3rd 1871
 on the Iron Screw Ste^r Paradox Master W^m Lumley
 Tonnage 226 built at Glasgow When built 1858
 By whom built _____ Owners W^m France
 Port belonging to Gool Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Up^r Globe Dry dock
 Last Survey, No. 8813 Port Iron Classified A.1. S.S. No. 3/86
 2.71

REPAIRS, &c.

From damage by collision.

Renewed three lengths of plating on the port side at about midships just above the turn of the bilge. — two lengths of bulwark plating with angle iron at the upper edge. 12 ft in length. and bulwark rail of wood. Made good the plating, and all work in connection with the bridge over the deck. Made good the caulking of some few of the batts in the bottom. Cleaned her out, and repaid or coated the bottom, and the plating where necessary. —

Present Condition of the

Decks	good	Transoms	Rivets where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from the deck
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors	No. of 213. 18.24
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	efficient	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	When put on	"	Standing & Running Rigging	"
Engine Room Skylights	good	Caulking of	good	"		
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	good	"		
General Observations and Opinion,		Scuppers	good	"		
		Cargo and Main Hatchways	good	"		
		Hatches	good	"		

She is now as far as seen in good condition
 and is in my opinion entitled to remain as class'd A.1.
 Samuel Presnour

The Amount of Entry Fee.....£ 1 : — : 7 is received by me,
 Special..... 1 : 1 :
 Certificate (if required) : 5 :

Committee's Minute 28th December 1871
 Character assigned B

Parasol

REPORT OF SURVEY FOR REPAIRS

1. Name of the building: _____
2. Address: _____
3. City: _____
4. State: _____
5. Zip: _____

Page 1

1A

10/1/88

The following is a summary of the survey results for the building. The building is in good condition and no repairs are needed. The roof is in good condition and the walls are in good condition. The foundation is in good condition and the floors are in good condition. The plumbing is in good condition and the electrical system is in good condition. The heating system is in good condition and the air conditioning system is in good condition. The building is in good condition and no repairs are needed.

1. Name of the building: _____
2. Address: _____
3. City: _____
4. State: _____
5. Zip: _____

The following is a summary of the survey results for the building. The building is in good condition and no repairs are needed. The roof is in good condition and the walls are in good condition. The foundation is in good condition and the floors are in good condition. The plumbing is in good condition and the electrical system is in good condition. The heating system is in good condition and the air conditioning system is in good condition. The building is in good condition and no repairs are needed.



© 2019
Lloyd's Register
Foundation