

# 9674 ANNUAL SURVEYS.

Re 27/12/41  
18 71.

No. 11656 Survey held at Newcastle Date 29<sup>th</sup> November 18 71.  
 on the Iron Barge "Trinculo" Master E. Way  
 Tonnage 310 Built at Bristol When built 1858  
 By whom built Stothard Owners Charles Ellis  
 Port belonging to London Destined Voyage Buenos Ayres.  
 If Surveyed Afloat or in Dry Dock Dry Dock.

Last Survey, No. 8764 Port of Iron. Classed \*A1 2.71.  
 (S.S. No. 3-68)

The present Condition of the

Decks	<u>Good.</u>	Treenails	<u>Rivets</u>	<u>Good.</u>	Windlass and Capstan	<u>Good.</u>
Waterways	<u>do.</u>	Breasthooks and Stemson		<u>do.</u>	Pumps	<u>do.</u>
Comings	<u>do.</u>	Transoms, Pointers, and Crutches		<u>do.</u>	Boats	<u>Two in No. do.</u>
Upper Deck Beams & Fastenings	<u>do.</u>	Timbers of the Frame at the Openings		<u>do.</u>	Masts, Yards, &c.	<u>do.</u>
Lower Deck Beams & Fastenings	<u>do.</u>	<u>Framing</u> Ditto ditto at other places		<u>do.</u>	Sails	<u>Well found.</u>
Planksheers	<u>do.</u>	Keelsons		<u>do.</u>	Anchors	<u>No. of 3 B. 1 S. 2 H.</u>
Sheerstrakes	<u>do.</u>	Clamps and Shelves			Cables	<u>Complete</u>
Topsides	<u>do.</u>	Ceiling		<u>do.</u>	Hawsers and Warps	<u>Sufficient.</u>
Wales	<u>do.</u>	Rudder		<u>do.</u>	Standing & Running Rigging	<u>Good.</u>
<u>Plating</u> Plank (Bottom) and Counter	<u>do.</u>	Copper	<u>When put on</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where tried.

*This vessel's bottom has been scraped and coated. She appears to be in good condition, and fit in my opinion to remain as classed \*A1.*

Committee's Minute 29<sup>th</sup> Decr 18 71

J. H. Cooke.

Character assigned \*A1

*J. H. Cooke*

Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18 \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	
	<u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register Foundation  
Certificate (if required).

120450-0121