

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 139 No. 23/12 Survey held at Birkenhead Date, first Survey Nov-15 Last Survey Nov-28 1871  
 on the Iron S.S. "Orchis" Master Crawford  
 Tonnage 1165 built at Glasgow When built 1870 - 11 mo  
 By whom built Laurie Owners Hargrove & Co.  
 Port belonging to Liverpool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Afloat & in Messrs. Clove's graving dock  
 Last Survey, No. 8905 Port Iron. Classed 100 A 1 2/11

REPAIRS, &c. Now done through damage.

Part of the stem - about 23 feet long - including six plates on each side of same, & part of one frame in fore compartment - renewed, also one plate in the sheer strake renewed & two frames part renewed on Port side abreast of After hatch -  
 The bottom scraped & painted.

## Present Condition of the

Decks	Freeboards <u>Pivots</u>	Windlass and Capstan <u>Good &amp; efficient</u>
Waterways	Breasthooks and Stemson	Pumps <u>" "</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>" "</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>" "</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>seen from deck</u>
Planksheers	Keelsons	Sails <u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>4</u>
Topsides	Ceiling <u>Good</u>	Cables <u>efficient</u>
Wales	Rudder <u>Good</u>	Hawsers and Warps <u>where</u>
Plank (Bottom) and Counter	Copper <u>See</u> When put on <u>70</u>	Standing & Running Rigging <u>seen</u>
Engine Room Skylights <u>Good</u>	Caulking of	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	
Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>

## General Observations and Opinion,

I am in good condition & in my opinion eligible to remain as Classed


The Amount of Entry Fee.....£ 8 : " : " is received by me,

Special..... 2 : 2 : " 16/12/71 Wm. E. Wheeler

Certificate (if required) " : " : "

Committee's Minute Liverpool, 16th January 1872

Character assigned 100 A 1 - Record damage repair



© 2019

Lloyd's Register Foundation



REPORT OF SURVEY FOR REPAIRS

"  
Dachis  
"



© 2019

Lloyd's Register  
Foundation