

23/1/72

9775

REPORT of SURVEY for REPAIRS.

Rev 31/1/72

No. in
Reg. Book.

No. 23132 Survey held at Liverpool Date, first Survey 30 December Last Survey 25 January 1872

on the SHIP "MILLWALL" Master Black.

Tonnage 1175 built at London When built 1863. same.

By whom built Millwall S. Coy. Owners Houghton Smith & Co.

Port belonging to Liverpool. Destined Voyage Melbourne

If Surveyed Afloat or in Dry Dock Brunswick Dry Dock.

Last Survey, No. 8426 Port Iron. Classed * A.S.

S.S. 704.67.

11.70.

REPAIRS, &c.

S.S. 10.2. Survey -

Timbers and ceiling equal to three shakes the and aft. on each
Side removed - Bottom scraped and painted. Inside cemented where
required - Joints mudlaid found in good condition. Cables changed -
Rudder repaired -

Present Condition of the

Decks	good when seen	Foremast Ribs.	good when seen	Windlass and Capstan	good & sufficient
Waterways	"	Breasthooks and Stemson	"	Pumps	have same
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from look
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors	No. of 3 Bows. 15 beam 2 Kedges.
Topsides	"	Ceiling	"	Cables	300 fathoms complete
Wales	"	Rudder	"	Hawsers and Warps	good & sufficient when
Plank (Bottom) and Counter	"	Copper Plank When put on	1863.	Standing & Running Rigging	seen
Engine Room Skylights	✓	Caulking of		Cargo and Main Hatchways	good Hatches good.
Coal Bunker, Openings, Lids, &c.	✓	Bottom, Deck, & Waterways	good		
Scuppers	✓				

General Observations and Opinion,

She is now in good condition - Eligible in my opinion. to
remain as classed. marked. S.S. 10.2. 72.

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... 5 : 5 : - 30/1/72 James Purdie

Certificate (if required) - : - : -

Committee's Minute Liverpool 30th January 1872

Character assigned A 1 - S.S. 10.2 - 72

J. G. E.



© 2019

Lloyd's Register
Foundation

LRN 450-0221

REPORT of SURVEY for REPAIRS.

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32



Millwall © 2019 23132

Lloyd's Register Foundation